

INTERIM EVALUATION INSTRUMENT
SCHOOL FACILITY CONDITIONS EVALUATION

SCHOOL SITE

Yosemite High

Part XIII. Playground/School Grounds

Check the appropriate box that indicates a "yes", "no", or "n/a" (not applicable) response for each standard of good repair. A "no" response indicates a deficiency is present.

The playground equipment and school grounds appear to be clean, safe, and functional. The following are examples:	YES	NO	N/A	BUILDING/CLASSROOM	COMMENTS
a. Significant cracks, holes and deterioration are not found.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
b. Accumulated refuse is not found.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
c. Open "S" hooks, protruding bolt ends, and sharp points/edges are not found in the playground equipment.	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>		
d. Other:	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		

Part XIV. Other

	BUILDING/CLASSROOM

Part XV. Acknowledgement:

I am a representative of *Yosemite Unified*, and the information contained herein is true and correct to the best of my knowledge and the above findings were made during my review of this school site on *Oct 27* at _____ a.m./p.m.

PRINT NAME <i>Sally Condon</i>	TITLE <i>Operations Supervisor</i>
SIGNATURE <i>Sally Condon</i>	DATE <i>10/27/06</i>
TELEPHONE NUMBER <i>5596427414</i>	E-MAIL ADDRESS <i>scondon@yosemiteuhsd.com</i>